




41




41/41




41-41




61




65




61-65




41-65




61-41




41/61-41




61-41-41




41-41-65



GTD8





41-GTD8




41-GTD8

(AL) =6063-T5 Aluminum Frame Member







Casement / Casement Detail





Fixed / Casement Detail



Fixed / Fixed Detail





14

Structural Mull

566625

566625

566625

(AL)

(AL)

2 9/16"

5/8"

2 9/16"

1 7/8"

5 3/4"

D.L.O.

D.L.O.

15

Structural Mull

566225

566625

(AL)

(AL)

566625

566225

2 9/16"

5/8"


2 9/16"



1 7/8"

5 3/4"




D.L.O.

D.L.O.






STRAP ANCHOR



Intermittent strap
anchor field install

NAIL FIN



Gap in nail fin that
must be field sealed
after field mulling top
and bottom

